

ⓘ This is a sample report. Some items may not be applicable to all assets and photos may vary to other reports.

Dealer Pre-purchase inspection

Date completed: 31/05/2023

Nissan Navara PRO-4X Warrior D23







Vehicle Information

VIN
MNTCBNN340008796

Model Year
2021

Engine Number
YS234465553A

Build Date
08 / 2021

Odometer Reading
23555

RAV Entry
28 / 04 / 2021

Registration Number
CHI322

Registration Expiry
04 / 2024


Tyre Size
LT275/70 R17 / LT275/70 R17

Transmission Type
Automatic

Fuel Type
Diesel

Drive Type
4x4

Report Summary



Engine/Motor

★★★★☆ 4.0

[View more](#)

Interior

★★★★☆ 4.0

[View more](#)

Exterior

★★★★☆ 3.5

[View more](#)

Tyres

★★★★☆ 4.0

[View more](#)

Road Test

★★★★☆ 4.0

[View more](#)

Overall the vehicle presents well, with some normal wear and tear associated with the age and km's travelled. There are a few cosmetic issues to note, including a chip on the windscreen glass and holes drilled into roof rack. The vehicle drove well on the road test with no obvious unusual noises or issues with performance at the time.



Heath M
Inspector

A handwritten signature in black ink, consisting of a stylized 'H' followed by a series of loops and a long horizontal stroke.

Attention Required

Glass / Mirrors

★ ★ ★ ★ ★ 2.0

Stone chip evident to the front windscreen, general wear to the mirrors and glass consistent with the age and mileage.



4WD/AWD

★ ★ ★ ★ ★ 2.0

Minor function test only carried out, noticed abnormal noise from the 4WD system: further investigation and repairs required.



Full Report

Engine/Motor (4.0) 

Engine/Motor  4.0

Start-up Battery

     4.0

Battery test returned "OK" result at the time of inspection. This indicates the battery is working as expected, showing normal wear for age/mileage.



Engine Oil Leaks and Residue

     3.0

No obvious engine leaks from the engine bay or underneath the vehicle at the time of inspection. Restricted visibility due to engine top covers and lower trays fitted, unable to be removed during this inspection.



Drive Belt & Pulleys

★★★★☆ 4.0


Working well at the time of inspection. Normal wear evident to the components consistent with the age and mileage. View restricted, no abnormal operational noises detected.



Fluid Level

★★★★☆ 4.0

All visible fluid levels within range at the time of inspection, some discolouration detected.



Idle Noise

★★★★★ 5.0


Normal operational noise from the engine bay on warm start at the time of inspection. Cold start not checked at time of inspection.



Master Cylinder / ABS / Brake Booster

★★★★☆ 4.0

Normal wear evident to the master cylinder and ABS (if fitted) components consistent with the age and mileage displayed.



Hoses and Pipes

★★★★☆ 4.0

Normal wear evident to the visible hoses and pipes consistent with the age and mileage.



Engine/Motor Cooling System

★★★★☆ 4.0

Normal wear to the cooling system components consistent with the age and mileage displayed. No visible leaks detected at the time of inspection.



Ignition and Fuel Systems

★★★★☆ 4.0

Fuel and ignition systems functioning at the time of inspection. Normal wear evident to the system components consistent with the age and mileage.



Mountings

★★★★☆ 4.0

Normal wear evident to the visible mountings consistent with the age and mileage.

Interior ★ 4.0

Air Conditioning
★★★★★ 4.0

Air conditioning cold and working well at the time of inspection. Normal wear evident to the air conditioning components consistent with the age and mileage.



Seats & Seat Belts
★★★★★ 4.0

Working well at the time of inspection. Normal wear evident to the seats, belts, buckles and components consistent with the age and mileage.



2 Keys Present

No

Heater Demister

★★★★☆ 4.0

Working well at the time of inspection, all functions operational. Normal wear evident to the vents, heater, demister and components consistent with the age and mileage.



Horn and Steering Wheel

★★★★☆ 4.0

Horn in working order and condition at the time of inspection. Normal wear evident to the steering wheel and other visible components consistent with the age and mileage.



Dash Lights, Gauges and Charging Display

★★★★☆ 4.0

No abnormal warning lights on in the dash cluster, no faults logged into the vehicle electronics at the time, normal wear evident to the dashboard gauges and trims.



Washers & Wipers


★★★☆☆ 3.0

Working well at the time of inspection. General wear evident to the windscreen washers, wipers and components consistent with the age and mileage.

Interior Trims

★★★★☆ 4.0

Interior trims, carpet and roof lining in good visual condition, minor wear or marks evident, clean and tidy for the age and mileage.



Infotainment System

★★★★★ 5.0

Standard radio fitted, steering wheel audio controls, navigation and reverse camera, all in good working order.



Window Operation

★★★★☆ 4.0

All windows and window controls operational at the time of inspection. Normal wear evident to the window mechanisms, switches and components consistent with the age and mileage.



Exterior ★ 3.5

Frames, Members, and Underbody Parts

★★★★★ 4.0

Superficial wear and marks to the frames and members consistent with the age and mileage travelled. Normal wear and minor scuffs (underside of the front bumper bar and under tray) to the underbody components consistent with the age and mileage displayed.



Body Condition

★★★★★ 4.0

Vehicle presents well at the time, minor sundry marks and light scratches. All attempts are made to detect hail damage but weather and vehicle condition can minimize detection. It is the buyers responsibility to conduct a final inspection prior to purchase, as we can only advise on the condition at the time of inspection.



External Lights

★★★★☆ 4.0

All external lights working well at the time of testing, normal wear (for example: minor stone chips and light marks) to the exterior light lens consistent with the age and mileage.



Drive Shafts

★★★★☆ 4.0

Working well at the time of inspection. Normal wear evident to the visible driveshafts, boots and joint components consistent with the age and mileage.



Differential

★★★★☆ 4.0

Working well at the time of inspection. Normal wear evident to the differential and final drive components consistent with the age and mileage.



Rust

★★★★☆ 4.0

Normal light surface rust or corrosion to some of the underbody fasteners and components consistent with the age and mileage displayed. The scope of the inspection does not include removal of components, only what is visible at the time. Paint and underbody sealer may inhibit detection of rust and corrosion.

Glass / Mirrors

★★★★☆ 2.0

Stone chip evident to the front windscreen, general wear to the mirrors and glass consistent with the age and mileage.



Front & Rear Suspension

★★★★☆ 4.0

Normal wear evident to the front and rear suspension components including visible rubber bushes consistent with the age and mileage.



Transmission

★★★★☆ 4.0

Normal wear evident to the visible components consistent with the age and mileage. RedBook Inspect are unable to ascertain the amount of wear to the internal components of the transmission or gearbox.



Sunroof / Aerial / Convertible

★★★★☆ 3.0

Aerial working well at the time of inspection. Holes drilled into roof racks for bolting on accessories/racks.



Exhaust

★★★★☆ 4.0

In servicable condition at the time of inspection. Normal wear evident to the exhaust system components consistent with the age and mileage. Diesel Particulate Filters not checked during this inspection, unable to ascertain service life or reliability at the time of inspection.



Steering Components

★★★★☆ 4.0


Working well at the time of inspection. Normal wear evident to the steering gear, linkages and components consistent with the age and mileage.



Doors, Locks & Hinges

★★★★☆ 4.0

Normal wear and marks to the door, locks, hinges and seals consistent with the age and mileage.




Tyres ★ 4.0

Tyres & Wheel Rims

★★★★★ 4.0

Front and rear tyres have approx. 9.54mm tread remaining to the front and 10.03mm tread remaining to the rear. Tyres fitted to the vehicle complies with manufacturer speed and load rating requirements. Minor wear visible to wheel rims.



Brake Linings, Wheel Cylinders & Drums

Not Checked: Brake drums, cylinders, linings and components not checked during this inspection.

Brake Calipers, Hoses and Pipes

★★★★★ 4.0

Normal wear evident to the brake hoses, calipers and components consistent with the age and mileage.

Brake Pads & Discs

★★★★☆ 4.0

General wear to brake pads and discs. In servicable condition at time of inspection. The scope of the inspection is limited to an approximate and what is visible at the time. Brake disc thickness not measured during this inspection.



Spare Tyre / Rim

★★★★☆ 4.0

Spare tyre present and shows minor wear at time of inspection.



Park Brake

★★★★☆ 4.0

Working well at the time of inspection. Normal wear evident to the park brake and components consistent with the age and mileage.



Road Test ★ 4.0

Brake Operation

★★★★★ 4.0

Working well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Ease of Starting Idle

★★★★★ 5.0

Easy to start at time of inspection.

Logbooks Present

Yes

Engine Driving Noise

★★★★★ 4.0

No abnormal noises detected at time of inspection.

Gearbox Auto / Manual


★★★★★ 4.0

No abnormal noises detected at time of inspection.

Owner's Manual - Service Intervals

★★★★★ 4.0

Services up to date, stamped and documented into the booklet, owners manuals and folder present.



Steering / Suspension

★★★★★ 4.0

Speedometer

★★★★★ 5.0

Accurate at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.



Cruise Control

★★★★★ 5.0

Working well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.



Differential

★★★★☆ 4.0

No abnormal noises detected at time of inspection.

Exhaust Smoke / Emissions

★★★★☆ 4.0

In servicable condition at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

4WD/AWD

★★☆☆☆ 2.0

Minor function test only carried out, noticed abnormal noise from the 4WD system: further investigation and repairs required.



Engine/Motor Performance

★★★★☆ 4.0

Engine performing well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time

Rating guide

★ 4.5 ~ 5.0 Very good

Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age of vehicle.

★ 3.5 ~ 4.0 Good

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 2.5 ~ 3.0 Fair

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 1.5 ~ 2.0 Poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

★ 0.5 ~ 1.0 Very poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

Disclaimer

(a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.

(b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.

(c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.

(d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.

(e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.

(f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.

(g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <https://www.redbookinspect.com.au/terms-of-service>.