

ⓘ This is a sample report. Some items may not be applicable to all assets and photos may vary to other reports.

# Pre Purchase Inspection Report

Date completed: 30/04/2024

**Land Rover Range Rover Evoque D200 R-Dynamic SE L551**









Vehicle Information

VIN  
KMHJC81DMNU073505

Model Year  
MY21

Engine Number  
G4NLMU905677

Build Date  
04 / 2021

Odometer Reading  
9999

Entry / Compliance Date  
04 / 2024

Registration Number  
721EP6

Registration Expiry  
06 / 2024

Standard Tyre Size  
235/50 R20 / 235/50 R20

Transmission Type  
Automatic

Fuel Type  
Diesel

Drive Type  
4x4

---



Inspection Video


0:00

Some features in this report can only be accessed in the web version.

Start Sequence Video



Report Summary



Engine/Motor

★★★★☆ 4.5

[View more](#)

Interior

★★★★☆ 3.5

[View more](#)

Exterior

★★★★☆ 4.5

[View more](#)

Wheels and Tyres

★★★★☆ 3.0

[View more](#)

Road Test

★★★★☆ 4.0

[View more](#)



Overall this vehicle has presented in fair condition taking into consideration the age and kilometres travelled. While the vehicle performed well during the road test, there are a few items outlined in the report that should be considered when making your purchasing decision. All tyres are due to be replaced soon and there is evidence of an engine oil leak that needs attention. It would be beneficial to raise this with the seller when negotiating the sale price.



**Heath M**  
Inspector


*Red Book Inspection*

# Attention Required

## Tyres and Wheel Rims

★★★★★ 2.0

Very limited wear remaining to the front and rear tyres. Tyres fitted to the vehicle complies with manufacturer speed and load rating requirements. Alignment required, and tyres to be replaced.



# Full Report

Select category to view results

Engine/Motor (★ 4.5)

Engine/Motor ★ 4.5


External Belts and Pulleys  
★★★★★ 5.0

In good working order and condition at the time of inspection. View restricted, no abnormal operational noises detected.



Start-Up Battery Charge Test  
★★★★★ 5.0

Battery test returned "OK" result at the time of inspection. Battery appears in as new condition.



Engine Bay Fluid Levels

★★★★★ 4.0


All visible engine bay fluid levels within range at the time of inspection, some discolouration detected.



Master Cylinder / ABS / Brake Booster

★★★★★ 5.0

In good working order at the time of inspection.



Hoses, Pipes and Associated Mountings

★★★★★ 5.0

All visible hoses, pipes and associated mountings appear in good working condition at the time of inspection.





### Fluid Leaks and Residue

★★★★☆ 3.0

Small amount of engine fluid residue visible under engine bay: further diagnosis and investigation needed. Restricted visibility due to engine top covers and lower trays fitted, not removed during this inspection.



### Fuel / Charging System

★★★★★ 5.0

Fuel / charging system in good working condition and working order at the time of inspection.



### Engine Oil Level

★★★★☆ 3.0

Engine oil level within specifications however some discolouration detected, service and oil change recommended.





Fan, Radiator and Cap

★★★★☆ 4.0


Normal wear to the cooling system components consistent with the age and mileage displayed. No visible leaks detected at the time of inspection.



Mountings

★★★★☆ 4.0

Normal wear evident to the visible mountings consistent with the age and mileage.



Engine / Motor Noise

★★★★★ 5.0

Normal operational noise from the engine bay on both cold and warm start at the time of inspection.



### Start-Up Battery Health Test

★★★★★ 5.0

Battery test returned "OK" result at the time of inspection. Battery appears in as new condition.




---

### Ignition System

★★★★★ 5.0

Ignition system in good working condition and working order at the time of inspection.



Interior ★ 3.5

Washers and Wipers

★★★★★ 3.0

Visible streaking from windscreen wipers at time of testing. General wear evident to the windscreen washers, wipers and components consistent with the age and mileage.



Seats and Seat Belts

★★★★★ 5.0

In good working order and condition at the time of inspection.



Window Operation

★★★★★ 5.0

All windows and window controls operational and in as new condition at the time of inspection.

Dash Lights, Gauges and Charging Display

★★★★★ 5.0

No abnormal warning lights on in the dash cluster, no faults logged into the vehicle electronics at the time, dashboard and trims in good visual condition.





Interior Trims

★★★★★ 3.0

Interior trims, carpet and roof lining showing moderate wear, including scuffs, marks, minor stains and tears consistent with the age and mileage. Recommend raising topic when negotiating price with seller.





### Air Conditioning

★★★★★ 5.0

Air conditioning efficient and in good working order at the time of inspection.



### Radio Operation

★★★★★ 5.0

Standard radio fitted, steering wheel audio controls, navigation and reverse camera, all in good working order.



### Horn and Steering Wheel

★★★★☆ 4.0

Horn in working order and condition at the time of inspection. Normal wear evident to the steering wheel and other visible components consistent with the age and mileage.

### 2 Keys Present

Yes



### Front Windscreen Demister

★★★★☆ 4.0

In good working order and condition at the time of inspection.

Exterior ★ 4.5

Underbody, Frames and Members

★★★★★ 4.0

Superficial wear and marks to the frames and members consistent with the age and mileage travelled. Normal wear and minor scuffs (underside of the front bumper bar and under tray) to the underbody components consistent with the age and mileage displayed.



Exhaust System

★★★★★ 5.0

Exhaust system is in good working order and condition at the time of inspection.

Exterior Lights

★★★★★ 5.0

All exterior lights functioning at time of inspection.



Differential

★ ★ ★ ☆ ☆ 3.0

Working well at the time of inspection. General wear and tear evident to the differential and final drive components consistent with the age and mileage.

---

Glass and Mirrors

★ ★ ★ ★ ★ 5.0

All glass and mirrors in good working order and condition at the time of inspection.



Transmission Performance

★ ★ ★ ★ ★ 5.0

In good working order and visible condition at the time of inspection. RedBook Inspect are unable to ascertain the amount of wear to the internal components of the transmission or gearbox, but


---



Body Repairs

★★★★☆ 4.0

Vehicle presents well at the time, minor sundry marks and light scratches. All attempts are made to detect hail damage but weather and vehicle condition can minimize detection. It is the buyers responsibility to conduct a final inspection prior to purchase, as we can only advise on the condition at the time of inspection.



Rust

★★★★☆ 4.0

Minor light surface rust or corrosion to some of the underbody fasteners and components consistent with the age and mileage displayed. The scope of the inspection does not include removal of components, only what is visible at the time. Paint and underbody sealer may inhibit detection of rust and corrosion.



Steering Components

★★★★★ 4.0


Working well at the time of inspection. Normal wear evident to the steering gear, linkages and components consistent with the age and mileage.



Front and Rear Suspension Components

★★★★★ 4.0

Normal wear evident to the front and rear suspension components including visible rubber bushes consistent with the age and mileage.



Sunroof / Aerial / Convertible

★★★★★ 5.0

Sunroof in good working order and condition at the time of inspection.



Drive Shafts

★★★★★ 4.0

Working well at the time of inspection. Normal wear evident to the visible driveshafts, boots and joint components consistent with the age and mileage.

## Doors, Locks and Hinges

★★★★★ 5.0

Doors, locks, hinges and seals in good working order at the time of inspection.



Wheels and Tyres ★ 3.0

Tyres and Wheel Rims  
★★★★★ 2.0

Very limited wear remaining to the front and rear tyres. Tyres fitted to the vehicle complies with manufacturer speed and load rating requirements. Alignment required, and tyres to be replaced.



Brake Calipers, Hoses and Pipes  
★★★★★ 4.0

Normal wear evident to the brake hoses, calipers and components consistent with the age and mileage.

### Spare Tyre and Rim

★★★★★ 5.0

Spare tyre present and in as new condition at time of inspection.



---

### Park Brake

★★★★★ 5.0

Park brake is in good working order and condition at the time of inspection.





Road Test ★ 4.0

Exhaust Smoke

★★★★★ 3.0

Some blue smoke on acceleration detected, possibly caused by engine burning oil inside the combustion chamber. Possible related to engine oil leak/residue found. Further investigation/repairs required.

Engine / Motor Driving Noise

★★★★★ 5.0

No abnormal noises from the engine at the time of inspection.

Brake Operation

★★★★★ 4.0

Working well at the time of testing, limited to local area speed limits.

Logbooks Present

Yes

4WD/AWD

★★★★★ 4.0

Minor function test only carried out, normal wear evident to components, working well at time of inspection.

Gearbox Auto / Manual

★★★★★ 5.0

Driveline operated smoothly and as expected, working well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Steering and Suspension Performance

★★★★★ 4.0

Normal operational but minor free play detected in steering wheel, consistent with age and mileage displayed.

Speedometer Functionality

★★★★★ 5.0

Differential

★★★★☆ 4.0

No abnormal noises detected at time of inspection.

---

Owner's Manual - Service Intervals

★★★★★ 5.0

Services up to date, stamped and documented into the booklet, owners manuals and folder present.



Engine / Motor Performance

★★★☆☆ 3.0

Normal engine performance expected of this type of engine.

---

Ease of Idling

★★★★★ 5.0

Easy to start at time of inspection.

## Rating guide

### ★ 4.5 ~ 5.0 Very good

Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age of vehicle.

### ★ 3.5 ~ 4.0 Good

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

### ★ 2.5 ~ 3.0 Fair

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

### ★ 1.5 ~ 2.0 Poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

### ★ 0.5 ~ 1.0 Very poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

## Disclaimer

(a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the excluded items set out in Attachment 2 – Excluded Items List of the RedBook Inspect Service Terms available at <https://www.redbookinspect.com.au/terms-of-service> as applicable. below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection where applicable, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.

(b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.

(c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.

(d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, (i) RedBook Inspect's total liability to you arising under or relating to this service shall not exceed the greater of: (A) \$1,000; and (B) 5 times the total fees paid by you to RedBook Inspect for the service giving rise to the liability.

(e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of the this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.

(f) To the full extent permitted by law, (ii) RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.

(g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <https://www.redbookinspect.com.au/terms-of-service>.