

! This is a sample report. Some items may not be applicable to all assets and photos may vary to other reports.

Ultimate Pre Purchase Inspection


Date completed: 24/04/2024

Hyundai Tucson



[REDACTED]

[REDACTED]



Vehicle Information

VIN
KMHJC81DMNU073505

Engine Number
G4NLMU905677

Build Date
07 / 2021

Odometer Reading
49320

Entry / Compliance Date
08 / 2021

Registration Number
721EP6

Registration Expiry
06 / 2024

Inspection Video

0:00

Some features in this report can only be accessed in the web version.

Start Sequence Video

Walkthroughs

0:00

Some features in this report can only be accessed in the web version.

Engine / Motor Bay

Some features in this report can only be accessed in the web version.


Exterior

0:00

Some features in this report can only be accessed in the web version.

Interior

Report Summary



Engine/Motor

★★★★★ 4.0

[View more](#)

Interior

★★★★★ 4.0

[View more](#)

Exterior

★★★★★ 4.0

[View more](#)

Wheels and Tyres

★★★★★ 4.0

[View more](#)

Road Test

★★★★★ 4.0

[View more](#)

66

Overall, this vehicle has been rated 4 stars taking into consideration of age & kilometres travelled. Vehicle presents well at time of inspection.



Peter E
Inspector



Full Report

Select category to view results

Engine/Motor (★ 4.0)

Engine/Motor ★ 4.0

External Belts and Pulleys

★★★★★ 4.0

Working well at the time of inspection. Normal wear evident to the components consistent with the age and mileage. View restricted, no abnormal operational noises detected.



Fluid Leaks and Residue

★★★★★ 4.0

No visible or obvious fluid leaks from the engine bay or underneath the vehicle at the time of inspection. Restricted visibility due to engine top covers and lower trays fitted (if applicable), not removed during this inspection.



Fuel / Charging System

★★★★☆ 4.0


Fuel system functioning at the time of inspection. Normal wear evident to the system components consistent with the age and mileage.



Master Cylinder / ABS / Brake Booster

★★★★☆ 4.0

Normal wear evident to the master cylinder and ABS (if fitted) components consistent with the age and mileage displayed.



Fan, Radiator and Cap


★★★★☆ 4.0

Normal wear to the cooling system components consistent with the age and mileage displayed. No visible leaks detected at the time of inspection.




Ignition System
★★★★☆ 4.0

Ignition system functioning at the time of inspection. Normal wear evident to the system components consistent with the age and mileage.




Engine Oil Level
★★★★☆ 4.0

Engine oil level within range at the time of inspection, some discolouration detected.



Hoses, Pipes and Associated Mountings
★★★★☆ 4.0

Normal wear evident to the visible hoses, pipes and associated mountings consistent with the age and mileage.



Engine / Motor Noise

★★★★☆ 4.0


Normal operational noise from the engine bay on both cold and warm start at the time of inspection.



Start-Up Battery Charge Test

★★★★☆ 4.0

Battery test returned "OK" result at the time of inspection. This indicates the battery is working as expected, showing normal wear for age/mileage.



Engine Bay Fluid Levels

★★★★☆ 4.0


All visible engine bay fluid levels within range at the time of inspection.



Mountings

★★★★☆ 4.0

Normal wear evident to the visible mountings consistent with the age and mileage.



Start-Up Battery Health Test

★★★★☆ 4.0

Battery test returned "OK" result at the time of inspection. This indicates the battery is working as expected, showing normal wear for age/mileage.



Other

Inspection limited to various engine components due to covers fitted. General wear visable. Consistant with age & kms travelled.

Interior ★ 4.0

Air Conditioning
★★★★★ 4.0

Air conditioning cold and working well at the time of inspection. Normal wear evident to the air conditioning components consistent with the age and mileage.



Window Operation
★★★★★ 4.0

All windows and window controls operational at the time of inspection. Normal wear evident to the window mechanisms, switches and components consistent with the age and mileage.




Washers and Wipers
★★★★★ 4.0

Working well at the time of inspection. Normal wear evident to the windscreen washers, wipers and components consistent with the age and mileage.



Radio Operation
★★★★☆ 4.0

Standard radio fitted, superficial wear to the audio controls consistent with the age and KMs travelled.



Dash Lights, Gauges and Charging Display
★★★★☆ 4.0

No abnormal warning lights on in the dash cluster, no faults logged into the vehicle electronics at the time, normal wear evident to the dashboard gauges and trims.



2 Keys Present

No

Seats and Seat Belts
★★★★☆ 4.0


Working well at the time of inspection. Normal wear evident to the seats, belts, buckles and components consistent with the age and mileage.



Interior Trims

★★★★☆ 4.0

Interior trims, carpet and roof lining in good visual condition, minor wear or marks evident, clean and tidy for the age and mileage.



Horn and Steering Wheel

★★★★☆ 4.0

Horn in working order and condition at the time of inspection. Normal wear evident to the steering wheel and other visible components consistent with the age and mileage.



Front Windscreen Demister

★★★★☆ 4.0

Automatic Climate Control: Working well at the time of inspection, all functions operational. Normal wear evident to the vents, heater, demister and components consistent with the age and mileage.



Exterior ★ 4.0

Drive Shafts
★★★★☆ 4.0

Working well at the time of inspection. Normal wear evident to the visible driveshafts, boots and joint components consistent with the age and mileage.



Rust
★★★★☆ 4.0

No visible rust or corrosion to the vehicle at the time of inspection. The scope of the inspection does not include removal of components, only what is visible at the time. Paint and underbody sealer may inhibit detection of rust and corrosion.



Doors, Locks and Hinges
★★★★☆ 4.0

Normal wear and marks to the door, locks, hinges and seals consistent with the age and mileage.



Underbody, Frames and Members

★★★★☆ 4.0

Superficial wear and marks to the frames and members consistent with the age and mileage travelled. Normal wear and minor scuffs (underside of the front bumper bar and under tray) to the underbody components consistent with the age and mileage displayed.



Transmission Performance

★★★★☆ 4.0

Normal wear evident to the visible components consistent with the age and mileage. RedBook Inspect are unable to ascertain the amount of wear to the internal components of the transmission or gearbox.



Exhaust System

★★★★☆ 4.0

In servicable condition at the time of inspection. Normal wear evident to the exhaust system components consistent with the age and mileage.



Body Repairs

★★★★☆ 4.0

Vehicle presents well at the time, minor sundry marks and light scratches. All attempts are made to detect hail damage but weather and vehicle condition can minimize detection. It is the buyers responsibility to conduct a final inspection prior to purchase, as we can only advise on the condition at the time of inspection.



Steering Components

★★★★☆ 4.0

Working well at the time of inspection. Normal wear evident to the steering gear, linkages and components consistent with the age and mileage.



Sunroof / Aerial / Convertible

★★★★☆ 4.0

Aerial working well at the time of inspection. Normal wear evident to the components consistent with the age and mileage.



Exterior Lights

★★★★☆ 4.0

All exterior lights working well at the time of testing, normal wear (for example: minor stone chips and light marks) to the exterior light lens consistent with the age and mileage.



Front and Rear Suspension Components

★★★★☆ 4.0

Normal wear evident to the front and rear suspension components including visible rubber bushes consistent with the age and mileage.



Glass and Mirrors

★★★★☆ 4.0

Front windscreen condition consistent with age and mileage. Mirrors working well at the time.



Wheels and Tyres ★ 4.0

Park Brake
★★★★★ 4.0

Working well at the time of inspection. Normal wear evident to the park brake and components consistent with the age and mileage.



Spare Tyre and Rim
★★★★★ 5.0

Spare tyre present and in as new condition at time of inspection.



Tyres and Wheel Rims

★★★★★ 3.0

General wear to the front and rear wheel tyres with approx. 3-4mm tread remaining to the front and approx. 3-4mm tread remaining to the rear. Tyres fitted to the vehicle complies with manufacturer speed and load rating requirements. Minor wear visible to wheel rims.?



Brake Calipers, Hoses and Pipes

★★★★★ 4.0

Normal wear evident to the brake hoses, calipers and components consistent with the age and mileage.

Road Test ★ 4.0

Exhaust Smoke

★★★★★ 4.0

In servicable condition at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Engine / Motor Driving Noise

★★★★★ 4.0

No abnormal noises detected at time of inspection.

Brake Operation

★★★★★ 4.0

Working well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Logbooks Present

Yes

Speedometer Functionality



★★★★★ 4.0

Normal operation of speedometer on roadtest, minor wear/scratches to cluster but otherwise working well at time of testing.

Owner's Manual - Service Intervals

★★★★★ 4.0

Services up to date, stamped and documented into the booklet, owners manuals and folder present.



Ease of Idling

★★★★★ 5.0

Steering and Suspension Performance

★★★★☆ 4.0

No abnormal noises detected at time of inspection.

Gearbox Auto / Manual

★★★★☆ 4.0

No abnormal noises detected at time of inspection.

Engine / Motor Performance

★★★★☆ 4.0

Engine performing well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time

Differential

★★★★☆ 4.0

No abnormal noises detected at time of inspection.

Rating guide

★ 4.5 ~ 5.0 Very good

Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age of vehicle.

★ 3.5 ~ 4.0 Good

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 2.5 ~ 3.0 Fair

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 1.5 ~ 2.0 Poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

★ 0.5 ~ 1.0 Very poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

Disclaimer

(a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.

(b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.

(c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.

(d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.

(e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.

(f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.

(g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <https://www.redbookinspect.com.au/terms-of-service>.