

ⓘ This is a sample report. Some items may not be applicable to all vehicles and photos may vary to other reports.

Pre Purchase Inspection Report

Date completed: 31/08/2022

Land Rover Range Rover Evoque TD4 110kW SE L538







Vehicle Information

VIN
TEST010101

Model Year
2018

Engine Number
SAMPLEENGINE

Build Date
10 / 2018


Odometer Reading
12765

Compliance Date
03 / 2019

Registration Number
SMPL01

Registration Expiry
08 / 2022

Report Summary



Engine

★★★★★ 5.0

[View more](#)

Interior

★★★★★ 4.0

[View more](#)

Exterior

★★★★★ 4.0

[View more](#)

Tyres

★★★★★ 5.0

[View more](#)

Road Test

★★★★★ 5.0

[View more](#)

Overall this vehicle has been rated 4.5 stars taking into consideration age and kilometres travelled. Vehicle presents in good condition however and interior clean is due. Some minor cosmetic imperfections as detailed in the report tabs below but no major damage present.



Heath M
Inspector

A handwritten signature in black ink, appearing to read 'Heath M', written in a cursive style.

Some features in this report can only be accessed in the web version.

Full Report

Engine (5.0) 

Engine ★ 5.0

Hoses, Pipes & Mountings

★★★★★ 5.0

In good working order and condition at the time of inspection.

Fluid Leaks

★★★★★ 5.0

No visible fluid leaks from the engine bay or underneath the vehicle at the time of inspection. Restricted visibility due to engine top covers and lower trays fitted (if applicable), not removed during this inspection.

Ignition System

★★★★★ 5.0

In good working order and condition at the time of inspection.

Fluid Level

★★★★☆ 4.0

All visible fluid levels within range at the time of inspection.



Master Cylinder / ABS / Brake Booster

★★★★★ 5.0

In good working order at the time of inspection.



Fuel System


★★★★★ 5.0

In good working order and condition at the time of inspection.

Battery

★★★★☆ 4.0

Working as expected, showing normal wear for age/mileage.



Noise

★★★★★ 5.0

Normal operational noise from the engine bay, OK at the time of inspection.



Drive Belt & Pulleys

★★★★★ 5.0

In good working order and condition at the time of inspection.

Water Pump, Fan, Radiator & Cap

★★★★★ 5.0

Cooling system in good working order at the time of inspection.

Other

Engine runs well for age and mileage travelled. All visible fluids within specifications at time of inspection.

Interior ★ 4.0

Seats & Seat Belts
★★★★★ 5.0

Leather seats. In good working order and condition at the time of inspection.



Doors, Locks & Hinges
★★★★★ 5.0

2 keys/remotes sighted and tested. Doors, locks and hinges in good working order at the time of inspection.



2 Keys Present

Yes

All Lights

★★★★☆ 4.0

All lights working well at the time of testing, normal wear (for example: minor stone chips and light marks) to the exterior light lens consistent with the age and mileage.



Heater Demister

★★★★★ 5.0

In good working order and condition at the time of inspection.

Washers & Wipers

★★★★★ 5.0

Windscreen wipers and washers are in good working order and condition at the time of inspection.

Window Operation

★★★★★ 5.0

In good working order and condition at the time of inspection.

Radio

★★★★★ 5.0

Standard radio fitted, steering wheel audio controls, navigation and reverse camera, all in good working order.



Air Conditioning

★★★★★ 5.0

Air conditioning cold and in good working order at the time of inspection.



Rear Window Demister

★★★★★ 5.0

Switch/ light working well at the time of inspection. Normal wear evident to the rear demister and components consistent with the age and mileage. Unable to check the rear heating element during this inspection.

Horn

★★★★★ 5.0

In good working order and condition at the time of inspection.

Dash Lights & Gauges

★★★★★ 5.0

No abnormal warning lights on in the dash cluster, no faults logged into the vehicle electronics at the time, dashboard and trims in good visual condition.



Other Trims

★★★★★ 3.0

Interior trims, carpet and roof lining showing general wear, including scuffs, marks, minor stains and tears consistent with the age and mileage. Recommend clean and vacuum at least, buyer to view prior to purchase.



Other

Recommend detail and clean. All electrics tested and working.

Exterior ★ 4.0

Glass / Mirrors
★★★★★ 5.0

In good working order and condition at the time of inspection.

Rust
★★★★★ 5.0

No visible rust or corrosion to the vehicle at the time of inspection. The scope of the inspection does not include removal of components, only what is visible at the time. Paint and underbody sealer may inhibit detection of rust and corrosion.

Drive Shafts
★★★★★ 5.0

Driveshafts and joints are in good working order and condition at the time of inspection.

Exhaust
★★★★★ 5.0

Exhaust system is in good working order and condition at the time of inspection.

Body Repairs
★★★★★ 4.0

Vehicle presents well at the time, sundry minor marks and light scratches. Minor cosmetic marks on rear drivers side door. All attempts are made to detect hail damage but weather and vehicle condition can minimize detection. It is the buyers responsibility to conduct a final inspection prior to purchase, as we can only advise on the condition at the time of inspection.



Differential
★★★★★ 5.0

Differential is in good working order and condition at the time of inspection.

Sunroof / Aerial / Convertible

★★★★★ 5.0

Aerial/ sunroof/ convertible (as applicable) in good working order and condition at the time of inspection.



Front & Rear Suspension

★★★★★ 5.0

Front and rear suspension is in good working order and condition at the time of inspection.



Steering Components

★★★★★ 5.0

Steering is in good working order and condition at the time of inspection.

Transmission

★★★★★ 5.0

In good working order and visible condition at the time of inspection. Unable to check transmission/ gearbox fluid condition or level due to no dipstick fitted

Frames & Members

★★★★★ 5.0

Frames and members are in good working order at the time of inspection.



Under Body Parts

★★★★★ 5.0

Normal wear and minor scuffs (underside of the front bumper bar and under tray) to the underbody components consistent with the age and mileage displayed.



Tyres ★ 5.0

Brake Hose Calipers / Pipes

★★★★★ 5.0

Brake calipers, hoses and pipes are in good working order and condition at the time of inspection.

Park Brake

★★★★★ 5.0

Park brake is in good working order and condition at the time of inspection.

Wheel Bearings

★★★★★ 5.0

Wheel bearings appear to be in good working order and condition at the time of inspection.

Spare Tyre / Rim

★★★★★ 5.0


Ok at time of inspection.



Tyres & Wheel Rims

★★★★★ 5.0

Front and rear tyres in good working order and have approx. 85% tread remaining. Wheel rims are in good condition.



Brake Pads & Discs

★★★★★ 5.0

OK at time of inspection (the scope of the inspection is limited to an approximate and what is visible at the time, Brake disc thickness not measured during this inspection).



Other

Original Michelin tyres fitted all round. All in good roadworthy condition

Road Test ★ 5.0

Speedometer

★★★★★★ 5.0

OK at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Cruise Control

★★★★★★ 5.0

OK at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Gearbox Auto / Manual

★★★★★★ 5.0

Driveline operated smoothly and as expected, OK at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Differential

★★★★★★ 5.0

OK at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Engine Performance

★★★★★★ 5.0

OK at time of inspection.

Camshaft / Drive Belt

Not Checked: Engine Timing belt, timing chain, gears, camshaft and associated components not checked during this inspection.

Steering / Suspension

★★★★★ 5.0

OK at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.



Exhaust Smoke / Emissions

★★★★★ 5.0

OK at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.


Logbooks Present

Yes

Owner's Manual - Service Intervals

★★★★★ 5.0

Services up to date, stamped and documented into the booklet, owners manuals and folder present.



Ease of Starting Idle

★★★★★ 5.0

OK at time of inspection.

Engine Noise

★★★★★ 5.0

No abnormal noises detected at time of inspection.

Brake Operation

★★★★★ 5.0

OK at the time of testing, braking from local speed limits only.

Other

Vehicle drove as expected with no untoward noises or performance issues

Rating guide

★ 4.5 ~ 5.0 Very good

Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age of vehicle.

★ 3.5 ~ 4.0 Good

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 2.5 ~ 3.0 Fair

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 1.5 ~ 2.0 Poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

★ 0.5 ~ 1.0 Very poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

Disclaimer

(a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.

(b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.

(c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.

(d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.

(e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of the this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.

(f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.

(g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <https://www.redbookinspect.com.au/terms-of-service>.