

ⓘ This is a sample report. Some items may not be applicable to all assets and photos may vary to other reports.

Lite Pre Purchase Inspection

Date completed: 12/04/2024

Hyundai Tucson







Vehicle Information

VIN
KMHJC81DMNU073505

Model Year
MY22

Engine Number
G4NLMU905677

Build Date
01 / 2021

Odometer Reading
47503

Entry / Compliance Date
08 / 2021

Registration Number
721EP6

Registration Expiry
06 / 2024

Standard Tyre Size
235/65 R17 104H / 235/65 R17 104H

Transmission Type
Automatic

Fuel Type
Petrol

Drive Type
FWD

Overall, this vehicle has rated well and is in good condition considering the age and kilometres travelled. The rear passenger side seat buckle requires attention, as mentioned in the report. Otherwise the vehicle presents well at time of inspection.



Heath M
Inspector

RB1

Full Report

Select category to view results

Engine/Motor (★ undefined)

Engine/Motor ★

Fan, Radiator and Cap
★★★★★ 4.0

Normal wear to the cooling system components consistent with the age and mileage displayed. No visible leaks detected at the time of inspection.



Master Cylinder / ABS / Brake Booster
★★★★★ 4.0

Normal wear evident to the master cylinder and ABS components consistent with the age and mileage displayed.



Engine Bay Fluid Levels

★★★★★ 5.0

All visible engine bay fluid levels within range at the time of inspection.



External Belts and Pulleys

★★★★★ 5.0


In good working order and condition at the time of inspection. View restricted, no abnormal operational noises detected.



Engine Oil Level

★★★☆☆ 3.0

Engine oil level within specifications however some discolouration detected, getting an oil change is highly recommended. Vehicle appears to be running fine however a service or repairs may be required if the oil has been this quality for an extended period of time.



Fluid Leaks and Residue

★★★★☆ 4.0

No visible or obvious fluid leaks from the engine bay or underneath the vehicle at the time of inspection. Restricted visibility due to engine top covers and lower trays fitted, not removed during this inspection.



Start-Up Battery Charge Test

★★★★☆ 3.0

Battery test returned "FAIR" result and started the engine OK at the time of inspection. Corrosion build up on battery terminals and limited service life remaining.



Engine / Motor Noise

★★★★★ 5.0

Normal operational noise from the engine bay on both cold and warm start at the time of inspection.



Interior ★

Horn and Steering Wheel

★★★★★ 5.0

Horn in good working order and condition at the time of inspection. No wear evident to the steering wheel or other visible components.




2 Keys Present

No

Dash Lights, Gauges and Charging Display

★★★★★ 5.0

No abnormal warning lights on in the dash cluster, no faults logged into the vehicle electronics at the time, dashboard and trims in good visual condition.



Seats and Seat Belts

★★★☆☆ 3.0

Rear passenger side seat belt difficult to release. It appears there might be a foreign object stuck in the buckle, which requires cleaning or replacement. All other seat belts working well at the time of inspection. Normal wear evident to the seats and components consistent with the age and mileage.



Exterior ★

Underbody, Frames and Members

★★★★★ 4.0


Superficial wear and marks to the frames and members consistent with the age and mileage travelled. Normal wear and minor scuffs (underside of the front bumper bar and under tray) to the underbody components consistent with the age and mileage displayed.



Exterior Lights

★★★★★ 4.0

All Exterior lights working well at the time of testing, general wear and oxidation to the exterior light lens consistent with the age and mileage.



Rust

★★★★★ 5.0

No visible rust or corrosion to the vehicle at the time of inspection. The scope of the inspection does not include removal of components, only what is visible at the time. Paint and underbody sealer may inhibit detection of rust and corrosion.



Glass and Mirrors

★★★★★ 5.0


All glass and mirrors in good condition and working well at the time of inspection.



Front and Rear Suspension Components

★★★★☆ 4.0

Normal wear evident to the front and rear suspension components including visible rubber bushes consistent with the age and mileage.



Wheels and Tyres ★

Tyres and Wheel Rims
★★★★★ 3.0

General wear to the front and rear tyres with approx. 3-4mm tread remaining to the front and approx. 3-4mm tread remaining to the rear. Tyres fitted to the vehicle complies with manufacturer speed and load rating requirements.



Spare Tyre and Rim
★★★★★ 4.0

Spare tyre present and shows minor wear at time of inspection.



Park Brake

★★★★★ 5.0

Park brake is in good working order and condition at the time of inspection.



Road Test ★

Engine / Motor Driving Noise

★★★★★ 4.0

No abnormal noises detected at time of inspection.

Ease of Idling

★★★★★ 5.0

Easy to start at time of inspection.

Gearbox Auto / Manual

★★★★★ 4.0

No abnormal noises detected at time of inspection.

Steering and Suspension Performance

★★★★★ 4.0

In good working order. No abnormal noises detected at time of inspection.

Exhaust Smoke

★★★★★ 4.0

In servicable condition at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Differential

★★★★★ 4.0

No abnormal noises detected at time of inspection.

Brake Operation



★★★★★ 5.0

Working well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time.

Owner's Manual - Service Intervals

★★★★★ 5.0

Services up to date, stamped and documented into the booklet, owners manuals and folder present.



Logbooks Present

Yes

Speedometer Functionality

★★★★☆ 4.0

Normal operation of speedometer on roadtest, minor wear/scratches to cluster but otherwise working well at time of testing.



Engine / Motor Performance

★★★★☆ 4.0

Engine performing well at the time of testing, limited road test due to local speed limits, road conditions and/or traffic at the time

Rating guide

★ 4.5 ~ 5.0 Very good

Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age of vehicle.

★ 3.5 ~ 4.0 Good

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 2.5 ~ 3.0 Fair

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age of vehicle.

★ 1.5 ~ 2.0 Poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

★ 0.5 ~ 1.0 Very poor

Item found not to be in working order and/or major signs of damage and/or wear & tear.

Disclaimer

(a) The inspection is VISUAL and non-mechanical only and RedBook Inspect will not be responsible for any defects that are latent discovered which were not visually apparent during the inspection. The inspection will cover the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, under body and a road test where possible. The inspection will specifically not cover the items set out below. No removal of parts or components is undertaken during the inspection process. You acknowledge that while RedBook Inspect's inspectors use accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age and condition of the vehicle at the time of inspection and any Report should be reviewed in this context. Vehicles are only road tested to speed limit of local area.

(b) The Report provided by RedBook Inspect to you is only current as at the time it is issued. It is a buyer's responsibility to conduct a visual inspection of the vehicle at the point of sale as RedBook Inspect can only advise on the condition of the vehicle at the time of inspection. The Report is not a roadworthy certificate and cannot be used as a roadworthy. You acknowledge that RedBook Inspect does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.

(c) RedBook Inspect will not be responsible for the terms of any transaction between any persons in relation to any vehicle inspected by RedBook Inspect or for resolving any dispute between any persons regarding any transaction.

(d) Subject to all applicable laws, RedBook Inspect does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you. To the full extent permitted by the law, RedBook Inspect will only be liable to you: (i) pursuant to any guarantee, right or contractual term that arises, is created or is implied by operation of law and that cannot be excluded PROVIDED THAT to the full extent permitted by law, any such liability of RedBook Inspect is limited, at RedBook Inspect's option, to (A) replacing or repairing the relevant goods (B) supplying goods equivalent to the relevant goods (C) supplying the relevant services again; or (D) paying the cost of such replacement, repairs or supply, subject always to subclause (g) below; or (ii) if Your claim arises from or in connection with any deliberate breach of these terms and conditions or fraud by RedBook Inspect.

(e) Except to the extent that liability cannot be excluded, RedBook Inspect, will not be liable to you for claims arising out of or in connection with your access and use of this Report whether arising in contract, tort (including negligence), indemnity, strict liability, breach of warranty or statute.

(f) To the full extent permitted by law, RedBook Inspect will not be liable to you for loss of use, production, profit, revenue, business, data, contractor anticipated savings or for delay or for any financing costs or increase in operating costs or any economic loss for any indirect or consequential loss or damage.

(g) Your use of this Inspection Report is subject to the RedBook Inspect Service Terms available at <https://www.redbookinspect.com.au/terms-of-service>.